

# SOLDERING & DESOLDERING



## Replacement Tips:

Please refer to 5SI-216N series Soldering tip on page.113

## Replacement Accessories:





Soldering Iron: 9SS-900N-SI

Hot Air Gun: 9SS-900NE-HG(AC 110~120V)/9SS-900NB-HG(AC 220~240V)

Soldering Iron Heater: 9SS-900N-HT

Hot Air Gun Heater: 5SS-989NE-H(AC 110~120V)

5SS-989NB-H(AC 220~240V)

IC Package	IC (mm)	Model No.
<b>Single</b> 		9SS-900-A1
		9SS-900-A2
		9SS-900-A3
<b>QFP</b> <b>(Quad Flat Pack)</b> 	10x10	9SS-900-B
	14x14	9SS-900-C
	17.5x17.5	9SS-900-D
	14x20	9SS-900-E
	28x28	9SS-900-F
<b>SOP</b> <b>(Small Outline Package)</b> 	4.4x10	9SS-900-H
	5.6x13	9SS-900-I
	7.5x15	9SS-900-J
	7.5x18	9SS-900-K
<b>PLCC</b> <b>(Plastic Leaded Chip Carrier)</b> 	17.5x17.5	9SS-900-L
	20x20	9SS-900-M
	25x25	9SS-900-N
	30x30	9SS-900-O